

Vacuum Heat Treatment

With three vacuum furnaces, turnaround time is 48 to 72 hours.
 One unit is reserved for tempering-only for single, double or triple tempering
 where surface condition is particularly important.
 Gas quench is always available in our certified vacuum furnaces.



- Tooling : A2 / D2 / H13 / M2 / S7 / etc.
- Aircraft Military : 13-8MO / 15-5PH / 17-4 PH, etc.
- Stainless : 304 / 410 / 420 / 440 / etc.
- Oil Quench : 4140 / 4340 / 1055 / 1075 / 1095, etc.
- Titanium / Inconel

- ✓ Vacuum Treatments
- ✓ Full Anneal
- ✓ Solution Anneal
- ✓ Sub Critical Anneal
- ✓ Hardening
- ✓ Tempering
- ✓ Normalizing
- ✓ Stress Relieve
- ✓ Quench with nitrogen, argon or oil



For further inquiries do not hesitate to contact us.